LUNKENHEIMER 125# and 150# S.P. Valves

Fig.126-Globe Solder Ends
P.O.A. **(not pictured)**



Fig.2140-Globe
Fig.2141-Angle
Screwed Bonnet
Screwed Ends
1/4" to 3"
Renewable Bronze Disc



Fig. 2144
Swing Check
Screwed Ends
3/8" to 3"
For 1/8" Use Fig. 554



Fig. 2142
Lift Check Screw Ends
1/4" to 3"
Renewable Bronze Disc
For 1/8" Use Fig. 414



Fig.2153-Gate
Screwed Bonnet
Screwed Ends 1/4" to 3"
Fig.2133-Gate
Screwed Bonnet
Solder Ends 1/4" to 3"



Fig.123-Globe
Fig.214-Angle
1/8" to 3"
150lb.S.P.,
300lb.W.O.G.
Renewable "N-M-D"
(Non-Metallic Disc)



Fig.3151-Gate Union Bonnet Screwed Ends
1/2" to 2"
150lb.S.P.,
300lb.W.O.G.
Solid Wedge Disc
Rising Bronze Stem

Fig.2150-Gate
Screwed Bonnet
Screw Ends
1/4" to 2"
150lb.S.P., 300lb.W.O.G.
Double Wedge Disc
Rising Bronze Stem



Fig.231-Lift Check without spring
Fig.233-Lift Check with spring
1/8" to 2"
150lb.S.P., 300lb.W.O.G.
Renewable "N-M-D"
(Non-Metallic Disc)

Fig.230
Swing Check 1/2" to 2"

Lunkenheimer	1/4"	3/8"	1/2"	3/4"	1"	1 1/4"	1 1/2"	2"	2 1/2"	3"
2140 2141 2144										
2142 2153 2133										
123 214 3151										
2150 231 233 230										

LUNKENHEIMER 200# S.P. Valves



Fig.407-Globe
Regrinding
1/8" to 3"
Union Bonnet
Renewable Bronze Disc



Fig. LQ600-200-Globe
1/4" to 2"
200lb.S.P.,
400lb.W.O.G.
Brinalloy Seat and Disc



Fig.73-PS-Globe
1/4" to 3"
Plug Type
Bronze "Renewo"
Union Bonnet
Renewable 500 Brinell
Stwkss Steel Seat and
Disc



Fig.768-Gate
1/4" to 3"
Single Wedge Disc
Non-Rising Stem
Renewable Nickel
Alloy Seats and Disc
1" and larger

Teflon + Disc. No. 60



Fig.416-Ball Check
Horizontal 1/8" to 2"

Fig.418-Lift Check
Vertical
1/8" to 3"
Regrinding
Renewable Bronze
Disc

Lunkenheimer	1/4"	3/8"	1/2"	3/4"	1"	1 1/4"	1 1/2"	2"	2 1/2"	3"
407 LQ600-200 73PS										
768 416										
418 No. 60 Disc.										